

**DEPARTMENT OF TRANSPORTATION  
FEDERAL AVIATION ADMINISTRATION  
MERRILL FIELD AIRPORT TRAFFIC CONTROL TOWER  
1950 EAST 5<sup>TH</sup> AVENUE  
ANCHORAGE, ALASKA 99501**

ISSUED: September 1, 2005

EFFECTIVE: October 1, 2005

MERRILL ATCT LETTER TO AIRMEN NO. 05-03

SUBJECT: AREAS OF NON-VISIBILITY

CANCELLATION: September 30, 2007

Due to obstruction of vision created by trees and hangars, certain aircraft may not be visible to controllers in the airport traffic control tower in the following areas:

Portions of Taxiway Charlie between Taxiways November and Sierra.

Portions of Runway 16/34 between Taxiways November and Sierra.

Pilots are advised to use caution in these areas.



John J. Schommer  
Air Traffic Manager